

Section 3 - SETTING UP FOR WELDING

The following items are required:

- 1) A reel of wire of suitable size and type.
- 2) A suitable gun and cable assembly with a "Euro" connector and the correct tip and, if necessary gas nozzle for the consumable being used. (LINC Gun MIG gun is supplied).
- 3) Correct drive rolls for the wire size and type to be used. The REDI-MIG® 210c & 250c are supplied with a 0.8 - 0.9mm drive roller. The REDI-MIG® 250s, 325c & 325s are supplied with a 0.9 - 1.2mm drive roller. Drive rolls for other types and sizes are available as spare parts. (See table on page 16).
- 4) A work return cable and clamp. (Supplied)
- 5) Normal welding accessories including helmet or hand shield with suitable lens, gloves etc.
- 6) If a gas shielded process is to be used, a cylinder of appropriate shielding gas is required. (Regulator/flowmeter and hose are supplied.) If gas shielding is required, connect the gas hose.

Remember that gas cylinders may explode if damaged, so ensure that all gas cylinders are securely mounted. Ensure that the correct type and size wire feed rolls are fitted. In replacing wire feed rolls, ensure that the key and keyway are correctly positioned and tighten the knurled locking screw securely.

Fit a spool of appropriate wire onto the spool so that it turns clockwise as the wire is fed.

Carefully release the end of the wire from the spool ensuring that the released end is held to stop the wire from unravelling. Cut off the end kink to give a smooth straight end of wire.


Obtain a gap between the wire feed roll and the pressure roll by lifting the cam latch. Feed the wire end into the guide tube, between the drive rolls, and into the "Euro" connector guide until it protrudes about 20mm out of the front of the "Euro" connector.

Close the drive rolls by lowering the cam latch ensuring the rolls firmly hold the wire. Adjust the tension so that wire feeds smoothly. **Do not over tighten.**



























Fit the gun and cable assembly onto the "Euro" connector by slipping the end of wire into the cable wire hole.

Tighten the "Euro" connector lock ring.

Activate the power source; set the wire feed speed to 4 on the dial and press the gun trigger or wire inch push button (if fitted). The wire feed roll should turn, feeding the wire further up the gun and cable assembly. Ensure there are no kinks or sharp bends in the gun cable and hold the gun trigger or wire inch button until the wire emerges from the gun. It is good practice to remove the tip when first feeding a new coil of wire, then refitting over the wire and tightening. Cut off the end of the wire leaving 10mm to 15mm stick-out. Select required polarity. See Section 1.5








.024 in. 0.60 mm
.030 in. 0.80 mm
.036 in. 1.0 mm
.048 in. 1.2 mm
.060 in. 1.6 mm
.075 in. 2.0 mm
.105 in. 2.5 mm
.135 in. 3.5 mm
3/16 in. 5.0 mm
1/4 in. 6.0 mm
5/16 in. 8.0 mm

Suggested setting for welding with the REDI-MIG® 210c & 250c											
STEEL						ALUMINIUM					
DC- 			DC+ 			DC+					
Innershield® - FCAW NR-211 MP NR212			UltraMag® S6 / EasyMIG™ S6						SuperGlaze® 4043, 5356		
No Gas Required			77% Argon 23% CO ₂ *			100% CO ₂ *			100% Argon *		
Wire Diameter											
0.9mm		1.2mm		0.8mm		0.9mm		0.8mm		0.9mm	
											
0.9mm				2 4.5				3 4.5			
1.6mm	4 3.25	3 2.25	4 5	4 4	5 4.5	4 3.5	4 7	4 5.5			
3.0mm	5 3	4 2.5	5 4	6 4.25	6 4.5	6 4.25	5 7.75	6 5.5			
5.0mm	7 3.5	6 3	7 5.25	7 3.5	7 5.5	7 4	6 7.25	6 6.5			
8.0mm		7 3.5	8 6	8 4	8 6	8 4		7 5.5			
Wire Diameter											
0.9mm		1.2mm		0.8mm		0.9mm		1.2mm		0.9mm	
											
0.9mm	1 2.5		1 3	1 2.75		1 3					
1.6mm	2 3.5	2 3	2 4.25	2 4	2 3.5	2 5	2 3	1 8	1 5.5		
3.0mm	3 3.5	3 3	3 4.25	3 4	3 3.5	3 4.25	3 3	3 7.5	3 6		
5.0mm	4 3.75	4 3	4 5.5	4 5	4 3.25	4 4	4 3	5 7.75	5 6		
8.0mm		5 3.5	6 6	6 5	6 4	6 4.75	6 3.75		7 7		

CONSUMABLE PARTS

LINC Gun® LG240G (REDI-MIG 210c, 250c & 250s)		
Contact Tip M6 0.6mm	LG240G	KP10440-06
Contact Tip M6 0.8mm	LG240G	KP10440-08
Contact Tip M6 0.9mm	LG240G	KP10440-09
Contact Tip M6 1.2mm	LG240G	KP10440-12
Contact Tip M6 0.9mm Alum	LG240G	KP10441-09A
Contact Tip M6 1.0mm Alum	LG240G	KP10441-10A
Contact Tip M6 1.2mm Alum	LG240G	KP10441-12A
Nozzle 12mm	LG240G	KP10461-4
Tip Holder M6	LG240G	KP10455-1
Gas Diffuser	LG240G	KP10404-WT
Liner 0.8-1.0mm 4m	LG240G	KP10413-4M
Liner 1.0-1.2mm 4m	LG240G	KP10414-4M
Liner 1.2-1.6mm 4m	LG240G	KP10415-4M
Liner 0.8-1.0mm 4m Teflon	LG240G	KP10422-4M
Liner 1.0-1.2mm 4m Teflon	LG240G	KP10418-4M
DRIVE ROLLERS		
Drive Roller 0.6-0.8mm		AS4449-9
Drive Roller 0.8-0.9mm		AS4449-11
Drive Roller 0.9-1.2mm		AS4449-8
Drive Roller 1.0-1.2mm		AS4449-2
Drive Roller 0.8-1.0mm Alum Drive		AS4449-12
Drive Roller 0.9-1.2mm Alum		AS4449-10
Driver Roller 0.9-1.2mm FCW		AS4449-13
Driver Roller 1.2-1.6mm FCW		AS4449-4

Note: 4 drive systems require 2 drive rollers



AUS 1300 LINCOLN
NZ 0800 728 720

LINCOLN
ELECTRIC
THE WELDING EXPERTS®


.024 in. 0.60 mm
.030 in. 0.80 mm
.036 in. 1.0 mm
.048 in. 1.2 mm
.060 in. 1.6 mm
.075 in. 2.0 mm
.105 in. 2.5 mm
.135 in. 3.5 mm
3/16 in. 5.0 mm
1/4 in. 6.0 mm
5/16 in. 8.0 mm

Suggested setting for welding with the REDI-MIG® 250s, 325c & 325s											
STEEL											
ALUMINIUM											
DC-				DC+				DC+			
Innershield® - FCAW		UltraMag® S6 / EasyMIG™ S6		SuperGlaze® 4043, 5356							
NR-211 MP		NR212									
No Gas Required		77% Argon 23% CO ₂ *		100% CO ₂ *		100% Argon *					
Wire Diameter											
0.9mm		1.2mm		0.8mm		0.9mm		1.2mm		0.9mm	
1.2mm		0.8mm		0.9mm		1.2mm		0.9mm		1.2mm	
0.9mm	2			1 2		1 2		1 2			
1.6mm	2	2 1.5	3 3.5	3 3.25	3 2	3 3	3 2	1 6	1 6		
3.0mm	3	3 2	4 4	4 4	4 2.75	4 3	4 2.5	3 6.25	3 6.5		
5.0mm	4	4 2.5	5 5.5	5 4.25	5 3	5 3.75	5 3	4 8	4 7.5		
8.0mm		5 3	7 7	7 6	7 4		7 3.75		5 9		
ALUMINIUM											
Innershield® - FCAW NR211MP, NR212 DC-		UltraMag® S6 / EasyMIG™ S6		Outershield® - 71-CX, FCAW DC+		SuperGlaze® 4043, 5356					
No Gas Required		77% Argon 23% CO ₂ *		100% CO ₂ *		100% Argon *					
Wire Diameter											
1.2mm		0.8mm		0.9mm		1.2mm		0.9mm		1.2mm	
0.9mm	1-4	2.5	1-4	1.5		1-1	2.75				
1.6mm	1-8	3.5	1.7	3	1-7	2	2-3	3	2-2	2.75	1-1
3.0mm	3-4	4.5	2-4	3.5	2.5	3	2-4	2.5	2-2	2.5	2-2
5.0mm	3-6	4.5	3-4	5.75	3.5	5	3-6	3.5	3-2	4.5	3-1
8.0mm	4-7	7.5	4-3	9	4.2	5	4-3	4.5	4-3	6	2-5
											2-5
											2-5

*Note: REDI-MIG 325c & 325s Voltage setting refer to coarse and fine positions



AUS 1300 LINCOLN
NZ 0800 728 720



CONSUMABLE PARTS

LINC GUN LG240G (REDI-MIG 250s)		
Contact Tip M6 0.6mm	LG240G	KP10440-06
Contact Tip M6 0.8mm	LG240G	KP10440-08
Contact Tip M6 0.9mm	LG240G	KP10440-09
Contact Tip M6 1.2mm	LG240G	KP10440-12
Contact Tip M6 0.9mm Alum	LG240G	KP10441-09A
Contact Tip M6 1.0mm Alum	LG240G	KP10441-10A
Contact Tip M6 1.2mm Alum	LG240G	KP10441-12A
Nozzle 12mm	LG240G	KP10461-4
Tip Holder M6	LG240G	KP10455-1
Gas Diffuser	LG240G	KP10404-WT
Liner 0.8-1.0mm 4m	LG240G	KP10413-4M
Liner 1.0-1.2mm 4m	LG240G	KP10414-4M
Liner 1.2-1.6mm 4m	LG240G	KP10415-4M
Liner 0.8-1.0mm 4m Teflon	LG240G	KP10422-4M
Liner 1.0-1.2mm 4m Teflon	LG240G	KP10418-4M
LINC GUN LG360G (REDI-MIG 325c & 325s)		
Contact Tip M8 0.9mm	LG360G	KP10445-09
Contact Tip M8 1.2mm	LG360G	KP10445-12
Contact Tip M8 1.6mm	LG360G	KP10445-16
Contact Tip M8 0.9mm Alum	LG360G	KP10445-09A
Contact Tip M8 1.2mm Alum	LG360G	KP10445-12A
Nozzle 16mm	LG360G	KP10461-3
Tip Holder M8	LG360G	KP10456-1
Gas Diffuser	LG360G	KP10405-WT
Liner 0.8-1.0mm 4m	LG360G	KP10413-4M
Liner 1.0-1.2mm 4m	LG360G	KP10414-4M
Liner 1.2-1.6mm 4m	LG360G	KP10415-4M
Liner 0.8-1.0mm 4m Teflon	LG360G	KP10422-4M
Liner 1.0-1.2mm 4m Teflon	LG360G	KP10418-4M
Liner 1.2-1.6mm 4m Teflon	LG360G	KP10420-4M
Liner 1.2-1.6mm 4m Teflon/Bronze	LG360G	KP10419-4M
DRIVE ROLLERS		
Drive Roller 0.6-0.8mm		AS4449-9
Drive Roller 0.8-0.9mm		AS4449-11
Drive Roller 0.9-1.2mm		AS4449-8
Drive Roller 1.0-1.2mm		AS4449-2
Drive Roller 0.8-1.0mm Alum		AS4449-12
Drive Roller 0.9-1.2mm Alum		AS4449-10
Driver Roller 0.9-1.2mm FCW		AS4449-13
Driver Roller 1.2-1.6mm FCW		AS4449-4

Note: 4 drive systems require 2 drive rollers

Section 4 - WELDING



WARNING

When the gun trigger is pressed (2T mode on REDI-MIG 4s) or pressed and released the first time (4T mode on REDI-MIG 4s), the wire is at welding voltage. The wire should never touch the case of the wire feeder. If it does, it is possible for the wire to arc to the case.

Any wire overrun should be avoided.

REDI-MIG 4s – Put into 2T Step trigger mode

Select the output voltage required to suit the job by setting the rotary voltage switches. (Refer to REDI-MIG® Welding Guide for suggested settings).

Before beginning welding, ensure the wire protrudes from the gun tip by approximately 10-15mm. Ensure gas is turned on for gas shielded processes. Ensure welding shield and other protective clothing are in place. Present the protruding electrode just off the work. Maintain a steady grip on the gun, protect your eyes with a welding shield, then press and hold the gun trigger to create the arc.

If it is necessary to adjust the weld voltage, stop welding before changing the rotary voltage switches.

Adjust the wire feed speed as necessary to suit the job. At the completion of the weld, release the gun trigger and hold the gun over the weld pool to stop the arc.

REDI-MIG 4s – 4T Step trigger mode should only be used for long welds by experienced operators.

4.1 Changing Electrode Size and Type

When changing the electrode size or type, ensure the wire feed drive roll is the correct size and type for the electrode. Wire feed drive rolls have two grooves each of different sizes. Ensure the roll is located by the key.

When changing to aluminium welding a new drive roll, cable liner and contact tip should be used.

All required equipment for aluminium welding is supplied in the optional 1.2mm Aluminium Feeding Kit (for REDI-MIG® 210c & 250c use KA1440-4. for REDI-MIG® 250s, 325c & 325s use KA1440-5).

When changing to cored wire welding, a new drive roll should be used. All required equipment for cored wire welding is supplied in the optional 1.2mm Flux Cored Feeding Kit (for REDI-MIG® 210c & 250c use KA1440-4 and for REDI-MIG® 250s, 325c & 325s use KA1440-5).

Also check electrode polarity, as different processes may require different polarities.

Note: Ensure that the correct gun liner and contact tip are used for different wire sizes and processes. Change gun liner as necessary. See Section 6.5 Liner Removal, Installation and Trimming Instructions for LINC Gun® 240 & 360 MIG guns.

Available Drive Rolls

Part No.	Size (mm)	Use with
AS4449-9	0.6 - 0.8	Solid Wire
AS4449-11	0.8 - 0.9	Solid Wire*
AS4449-8	0.9 - 1.2	Solid Wire**
AS4449-2	1.0 - 1.2	Solid Wire
AS4449-5	0.8 - 1.0	Aluminium Wire
AS4449-12	0.9 - 1.2	Aluminium Wire
AS4449-3	0.8 - 1.0	Cored Wire
AS4449-13	0.9 - 1.2	Cored Wire
AS4449-4	1.2 - 1.6	Cored Wire

* Standard on REDI-MIG® 210c and 250c

** Standard on REDI-MIG® 250s, 325c & 325s.

4.2 Adjusting Spool Tension

The spool should stop rotating when the wire feed roll stops. Overrun of the spool can cause the coil of wire to unravel. The spool hub should be tensioned so that it neither drags nor overruns. The tension can be set by adjusting the large nut inside the hub with a tube spanner.

Section 5 - LEARNING TO WELD

No one can learn to weld simply by reading about it. Skill comes only with practice. The following pages will help the inexperienced operator to understand welding and develop this skill.

5.1 The Arc-Welding Circuit

The operators knowledge of arc welding must go beyond the arc itself. The operator must know how to control the arc, and this requires a knowledge of the welding circuit and the equipment that provides the electric current used in the arc. The circuit begins where the gun cable is attached to the welding machine. Current flows through the gun cable, gun, and contact tip, to the wire and across the arc. On the work side of the arc, current flows through the base metal to the work cable and back to the welding machine. This circuit must be complete for the current to flow.

This machine's welding circuit has a voltage output of 45 volts DC maximum. This voltage is quite low and is only present when the gun trigger is depressed.

To weld, the work clamp must be tightly connected to clean base metal. Remove paint, rust, dirt or oil as necessary and connect the work clamp as close as possible to the area you wish to weld. This helps prevent current from going through an unwanted path. Avoid allowing the welding circuit to pass through hinges, bearings, electronic components, or similar devices that can be damaged. Always disconnect electrical devices before welding upon them.



FUMES AND GASES can be dangerous

Fumes and slag generated from electrodes recommended for use with this welding machine can be toxic.

- Avoid contact with eyes and skin.
- Do not take internally.
- Keep out of reach of children.
- Follow all safety precautions found in this operating manual.


The gun and cable assembly is held by the operator who guides the automatically fed wire along the joint, maintaining a contact tip to work distance of about 10 - 12 mm This is called electrical stickout. This electrical stickout (ESO) must be properly maintained by the operator. The electric arc is made in the gap between the work and the tip end of a small diameter wire. When the power source is properly set, the arc gap is maintained automatically.

Arc welding is a manual skill requiring a steady hand, good physical condition, and good eyesight. The operator controls the welding arc, and, therefore, the quality of the weld made.

5.2 The Self-Shielded (Gasless) FCAW Welding Arc (DC-)

Figure 1 illustrates the action taking place in the self shielded gasless FCAW welding arc. It closely resembles what is actually seen while welding.

Figure 1



The “arc stream” is seen in the middle of the picture. This is the electric arc created by the electric current flowing through the space between the end of the wire electrode and the base metal. The temperature of this arc is about 3300°C, which is more than enough to melt metal.

The arc is very bright, as well as hot, and cannot be looked at with the naked eye without risking painful injury. The very dark lens, specifically designed for arc welding must be used with the hand or face shield whenever viewing the arc.

The arc melts the base metal and actually digs into it much as water through a nozzle on a garden hose digs into the earth. The molten metal forms a molten pool or crater and tends to flow away from the arc. As it moves away from the arc, it cools and solidifies.

The function of the cored wire electrode is much more than simply to carry current to the arc. The wire core is composed of fluxes and/or alloying ingredients around which a steel sheath has been formed. It is simply a stick electrode turned inside out in a continuous wire form.

The cored wire melts in the arc and tiny droplets of molten metal shoot across the arc into the molten pool. The wire sheath provides additional filler metal for the joint to fill the groove or gap between the two pieces of base metal.

The core materials also melt or burn in the arc and perform several functions. They make the arc steadier, provide a shield of smoke-like gas around the arc to keep oxygen and nitrogen in the air away from the molten metal, and provide a flux for the molten pool. The flux picks up impurities and forms the protective slag on top of the weld during cooling.


After running a weld bead, the slag may be removed with a chipping hammer and wire brush. This improves appearance and allows for inspection of the finished weld.

Machine size and output characteristics limit the size and type of wire electrode which can be used.

5.3 The GMAW (MIG) Welding Arc (DC+)

Figure 2 illustrates the GMAW (MIG) welding arc. Solid wire does not contain fluxes or ingredients to form its own shielding and no slag forms to protect the molten weld metal. For this reason, a continuous even flow of shielding gas is needed to protect the molten weld metal from atmospheric contaminants such as oxygen and nitrogen. Shielding gas is supplied through the gun and cable assembly, through the gas nozzle and into the welding zone.

Figure 2



When comparing the GMAW and FCAW processes, you can see that the principal difference between the two lies in the type of shielding used. GMAW uses gas for shielding, thus we have Gas Metal Arc Welding. FCAW uses the melting or burning of the core ingredients for shielding, and is thus termed Self-Shielded Flux Cored Arc Welding.

Gas Metal Arc Welding (MIG) is capable of welding a wide range of mild steels in all positions, however, more skill is required for out-of-position welding with the GMAW process.

5.4 Process Selection

By gaining knowledge of the differences between the two processes, you will be able to select the best process for the job you have at hand. In selecting a process, you should consider:

For GMAW (MIG) Process

1. Can I afford the extra expense, space, and lack of portability required for gas cylinders and gas supply?
2. Do I require clean, finished-looking welds?

If you have answered yes to all the above questions GMAW may be the process for you. If you have answered no to any of the above questions, then you should consider using the FCAW process.

For FCAW (Innershield) Process

1. Do I want simplicity and portability?
2. Will welding be performed outdoors or under windy conditions?
3. Do I require good all position welding capability?

5.5 Common Metals

Most metals found around the farm, small shop or home are low carbon steel, sometimes referred to as mild steel. Typical items made with this type of steel include most sheet metal, plate, pipe and rolled shapes such as channels and angle irons. This type of steel can usually be easily welded without special precautions. Some steels, however, contain higher carbon levels or other alloys and are more difficult to weld. Basically, if a magnet sticks to the metal and you can easily cut the metal with a file, chances are good that the metal is mild steel and that you will be able to weld the material. In addition, aluminum and stainless steel can be welded using the an aluminum welding kit. For further information on identifying various types of steels and other metals, and for proper procedures for welding them, we suggest you purchase a copy of “New Lessons in Arc Welding”.

Regardless of the type of metal being welded, in order to get a quality weld, it is important that the metal is free of oil, paint, rust or other contaminants.

5.6 Machine Set up for the Self-Shielded (Gasless) FCAW Process

1. Ensure the machine has the correct drive roll and parts (all required parts for cored wire welding are supplied in the Innershield (Gasless) Welding Kit (for REDI-MIG® 210c & 250c use KA1441-4. For REDI-MIG® 250s, 325c & 325s use KA1441-5).
2. See the Welding Procedure Guide on the inside of wire feed section door for information on setting the controls.
3. Set the “Voltage” and “Wire Speed” controls to the settings suggested on the Welding Procedure Guide for the welding wire and base metal thickness being used.
4. Check that the polarity is correct for the welding wire being used. See Section 1.5 for instructions on changing polarity.
5. Connect work clamp to metal to be welded. Work clamp must make good electrical contact to the work piece. The work piece must also be grounded as stated in the “Arc Welding Safety Precautions” at the beginning of this manual.

5.7 Welding Techniques For The Self-Shielded (Gasless) FCAW Process

Four simple manipulations are of prime importance when welding. With complete mastery of the four, welding will be easy. They are as follows:


1. The Correct Welding Position

Figure 3 illustrates the correct welding position for right handed people. (For left handed people, it is the opposite.)

Hold the gun (of the gun and cable assembly) in your right hand and hold the shield with your left hand. (Left handers simply do the opposite.)

When using the FCAW Process, weld from left to right (if you are right handed). This enables you to clearly see what you are doing. (Left handers do the opposite.) Tilt the gun toward the direction of travel holding the electrode at an angle as shown in Figure 3.

Figure 3



When using an open arc process, it is necessary to use correct eye, head and body protection.

Protect yourself and others, read "ARC RAYS can burn" at the front of this manual.

2. The Correct Way To Strike An Arc

1. Be sure the work clamp makes good electrical contact to the work.
2. Position gun over joint. End of wire may be lightly touching the work.
3. Position face shield to protect face and eyes, close gun trigger, and begin welding. Hold the gun so that the contact tip to work distance is about 10 - 12 mm.
4. To stop welding, release the gun trigger and pull the gun away from the work after the arc goes out.
5. A ball may form at the tip end of the wire after welding. For easier restrikes the ball may be removed by feeding out a few inches of wire and simply bending the wire back and forth until it breaks off.
6. When no more welding is to be done, turn off the machine.


3. The Correct Electrical Stickout (ESO)

The electrical stickout (ESO) is the distance from the end of the contact tip to the end of the wire.

See Figure 4.

Once the arc has been established, maintaining the correct ESO becomes extremely important. The ESO should be approximately 10 - 12 mm long.

Figure 4




The easiest way to tell whether the ESO is the correct length is by listening to its sound. The correct ESO has a distinctive "crackling" sound, very much like eggs frying in a pan. A long ESO has a hollow, blowing or hissing sound. If the ESO is too short, you may stick the contact tip or nozzle to the weld puddle and/or fuse the wire to the contact tip.

4. The Correct Welding Speed

The important thing to watch while welding is the puddle of molten metal right behind the arc. See Figure 5. Do not watch the arc itself. It is the appearance of the puddle and the ridge where the molten puddle solidifies that indicates correct welding speed. The ridge should be approximately 10 mm behind the wire electrode.

Most beginners tend to weld too fast, resulting in a thin uneven, "wormy" looking bead. They are not watching the molten metal.


Figure 5



Helpful Hints

1. For general welding, it is not necessary to weave the arc, neither forward or backward nor sideways. Weld along at a steady pace. You will find it easier.
2. When welding on thin plate, you will find that you will have to increase the welding speed, whereas when welding on heavy plate, it is necessary to go more slowly in order to get good penetration.
3. When welding sheet metal 1.6 mm and lighter, heat buildup may cause part warpage and burn through. One way to eliminate these problems is to use the back-stepping method illustrated in Figure 6.

Figure 6




Practice

The best way of getting practice in the four skills that enable you to maintain:

1. Correct welding position
2. Correct way to strike an arc
3. Correct electrical stickout
4. Correct welding speed is to perform the following exercise.

Figure 7



For the REDI-MIG® 250c use the following:

Mild Steel Plate	3.0mm
Electrode	0.9mm Innershield 211 MP
Voltage Setting	3
Wire Feed Speed	3.5


Refer to Figure 7.

1. Learn to strike an arc by positioning the gun over the joint and touching the wire to the work.
2. Position face shield to protect face and eyes.
3. Depress gun trigger, hold gun so contact tip to work distance is about 10 to 12 mm and the gun is at proper angle.
4. After you strike the arc, practice the correct electrical stickout. Learn to distinguish it by its sound.
5. When you are sure that you can hold the correct electrical stickout, with a smooth “crackling” arc start moving. Look at the molten puddle constantly, and look at the “ridge” where the metal solidifies.
6. Run beads on a flat plate. Run them parallel to the top edge (the edge farthest away from you). This gives you practice in running straight welds, and also gives you an easy way to check your progress. The 10th weld will look considerably better than the first weld. By constantly checking on your mistakes and your progress, welding will soon be a matter of routine.

5.8 Machine Set Up for the GMAW (MIG) Process and Gas Shielded GCAW Processes

1. The REDI-MIG® comes ready for welding using the MIG process.
2. See the Procedure Welding Guide on the inside of wire feed section door for information on setting the controls.
3. Set the “Voltage” and “Wire Speed” controls to the settings suggested on the Procedure Welding Guide for the welding wire and base metal thickness being used. ’
4. Check that the polarity is correct for the welding wire being used. Set the polarity for DC(+) when welding with the GMAW (MIG) process. See Section 1.5 for instructions for changing polarity.
5. Check that the gas nozzle and proper size liner and contact tip are being used and that the gas supply is turned on. Set for 7 to 10 L/min. under normal conditions, increase to as high as 17 L/min. under drafty (slightly windy) conditions.
6. Connect work clamp to metal to be welded. Work clamp must make good electrical contact to the work piece. The work piece must also be grounded as stated in the “Arc Welding Safety Precautions” at the beginning of this manual.

Figure 8



5.9 Welding Techniques for the GMAW (MIG) Process

Four simple manipulations are of prime importance when welding. With complete mastery of the four, welding will be easy. They are as follows:

1. The Correct Welding Position

Figure 8 illustrates the correct welding position for right handed people. (For left handed people, it is the opposite.)

When GMAW (MIG) welding on sheet metal, it is important to use the “forehand” push technique.

Hold the gun (of the gun and cable assembly) in your right hand and hold the shield with your left hand. (Left handers simply do the opposite.) Weld from right to left (if you are right handed). This results in a colder weld and has less tendency for burn through.




When using an open arc process, it is necessary to use correct eye, head and body protection.

Protect yourself and others, read “ARC RAYS can burn” at the front of this manual.

2. The Correct Way To Strike An Arc

1. Be sure the work clamp makes good electrical contact to the work.
2. Position gun over joint. End of wire may be lightly touching the work.
3. Position face shield to protect face and eyes, close gun trigger, and begin welding. Hold the gun so that the contact tip to work distance is about 10 - 12 mm.
4. To stop welding, release the gun trigger and pull the gun away from the work after the arc goes out.
5. A ball may form at the tip end of the wire after welding. For easier restrikes, the ball may be removed by feeding out a few inches of wire and cutting off the end of the wire with wire cutters.
6. When no more welding is to be done, close the valve on the gas cylinder, momentarily operate the gun trigger to release gas pressure, then turn off the machine.

Figure 9



3. The Correct Electrical Stickout (ESO)

The electrical stickout (ESO) is the distance from the end of the contact tip to the end of the wire. See Figure 9.

Once the arc has been established, maintaining the correct ESO becomes extremely important. The ESO should be approximately 10 to 12 mm long.

The easiest way to tell whether the ESO is the correct length is by listening to its sound. The correct ESO has a distinctive “crackling” sound, very much like eggs frying in a pan. A long ESO has a hollow, blowing or hissing sound. If the ESO is too short, you may stick the contact tip or nozzle to the weld puddle and/or fuse the wire to the contact tip.


4. The Correct Welding Speed

The important thing to watch while welding is the puddle of molten metal right behind the arc. See Figure 10. Do not watch the arc itself. It is the appearance of the puddle and the ridge where the molten puddle solidifies that indicates correct welding speed. The ridge should be approximately 10 mm behind the wire electrode.

Most beginners tend to weld too fast, resulting in a thin, uneven, “wormy” looking bead. They are not watching the molten metal.

Helpful Hints

Figure 10



1. For general welding, it is not necessary to weave the arc, neither forward or backward nor sideways. Weld along at a steady pace. You will find it easier.
2. When welding on thin plate, you will find that you will have to increase the welding speed, whereas when welding on heavy plate, it is necessary to go more slowly in order to get good penetration.
3. When welding sheet metal 1.6mm and lighter, heat buildup may cause part warpage and burn through. One way to eliminate these problems is to use the back-stepping method illustrated in Figure 6.

Practice

The best way of getting practice in the four skills that enable you to maintain:

1. Correct welding position
2. Correct way to strike an arc
3. Correct electrical stickout
4. Correct welding speed

is to perform the following exercise.

Refer to Figure 4.

Refer to Figure 7.

For the REDI-MIG® 250s, use the following:

Mild Steel Sheet	(1.6 mm)
Electrode	0.9mm Ultramag S6 electrode Argon/CO ₂ Blend
Voltage Setting	1
Wire Feed Speed	2.75

1. Learn to strike an arc by positioning the gun over the joint and touching the wire to the work.
2. Position face shield to protect face and eyes.
3. Depress gun trigger, hold gun so contact tip to work distance is about 10-12 mm and the gun is at proper angle.
4. After you strike the arc, practice the correct electrical stickout. Learn to distinguish it by its sound.


stickout, with a smooth “crackling” arc, start moving. Look at the molten puddle constantly,

6. Run beads on a flat plate. Run them parallel to the top edge (the edge farthest away from you). This gives you practice in running straight welds, and also gives you an easy way to check your progress. The 10th weld will look considerably better than the first weld. By constantly checking on your mistakes and your progress, welding will soon be a matter of routine.

5.10 Joint Types and Positions

Five types of welding joints are: Butt Welds, Fillet Welds, Lap Welds, Edge Welds and Corner Welds. See Figure 10.

Figure 10



Of these, the Butt Weld and Fillet Weld are the two most common welds.


5.11 Butt Welds

Place two plates side by side, leaving a space approximately one half the thickness of the metal between them in order to get deeper penetration.

Securely clamp or tack weld the plates at both ends, otherwise the heat will cause the plates to move apart. See Figure 11.

Now weld the two plates together. Weld from left to right (if right handed and using self-shielded FCAW process). Point the wire electrode down in the crack between the two plates, keeping the gun slightly tilted in the direction of travel.

Figure 11



Watch the molten metal to be sure it distributes itself evenly on both edges and in between the plates.

5.12 Penetration

Unless a butt weld penetrates close to 100% of the metal thickness, a butt weld will be weaker than the material welded together. In the example shown in Figure 12, the total weld is only half the thickness of the material thus the weld is only approximately half as strong as the metal.

In the example shown in Figure 13, the joint has been welded so that 100% penetration could be achieved. The weld, if properly made, is as strong as or stronger than the original metal.

Figure 12






Figure 13



5.13 Fillet Welds

When welding fillet welds, it is very important to hold the wire electrode at a 45° angle between the two sides or the metal will not distribute itself evenly. The gun nozzle is generally formed at an angle to facilitate this. See Figure 14.

Figure 14



5.14 Welding In The Vertical Position


Welding in the vertical position can be done either vertical-up or vertical-down. Vertical-up is used whenever a larger, stronger weld is desired. Vertical-down is used primarily on sheet metal 4.0mm and under for fast, low penetrating welds.

5.15 Vertical-up And Overhead Welding

The problem, when welding vertical-up, is to put the molten metal where it is wanted and make it stay there. If too much molten metal is deposited, gravity will pull it downwards and make it "drip". Therefore, a certain technique has to be followed.

When welding out-of-position, run stringer beads. Don't whip, break the arc, move out of the puddle, or move too fast in any direction. Use Wire Feed Speed (WFS) in the low portion of the range. The general technique and proper gun angle are illustrated in Figure 15.

Generally, keep the electrode nearly perpendicular to the joint as illustrated. The maximum angle above perpendicular may be required if porosity becomes a problem.




5.16 Vertical-down Welding

Refer to Figure 16 Vertical-down welds are applied at a fast pace. These welds are therefore shallow and narrow and, as such, are excellent for sheet metal. Vertical-down welds may be applied to 4.0 mm and lighter material.

Use stringer beads and tip the gun in the direction of travel so the arc force helps hold the molten metal in the joint. Move as fast as possible consistent with desired bead shape.

The important thing is to continue lowering the entire arm as the weld is made so the angle of the gun does not change. Move the electrode wire fast enough that the slag does not catch up with the arc. Vertical-down welding gives thin, shallow welds. It should not be used on heavy material where large welds are required.


Figure 16




WARNING

Use of this unit on thicker materials than recommended may result in poor welds. The welds may "look" good, but may just be "sitting" on top, of the plate. This is called "Cold Lapping" and will result in weld failure.

5.17 Troubleshooting Welds




Good welds have excellent appearance.



To Eliminate Porosity (in order of importance):

1. Turn on gas supply, if used
2. Decrease voltage.
3. Increase stickout.
4. Increase WFS (wire feed speed).
5. Decrease torch angle.
6. Decrease travel speed.

Note: Always be sure the joint is free from moisture, oil,




rust, paint or other contaminants.

To Eliminate a Ropy Convex Bead

(in order of importance):

1. Increase voltage
2. Decrease stickout.
3. Decrease WFS (wire feed speed).
4. Decrease travel speed.
5. Decrease torch angle.
6. Check for correct gas, if used.

To Reduce Spatter (in order of importance):



1. Increase voltage.
2. Increase torch angle.
3. Decrease stickout.
4. Increase WFS (wire feed speed).
5. Decrease travel speed.
6. Check for correct gas, if used.

To Correct Poor Penetration (in order of importance):

1. Decrease stickout.
2. Increase WFS (wire feed speed).
3. Increase voltage.
4. Decrease speed.
5. Decrease torch angle.
6. Check for correct gas, if used.

If Arc Blow Occurs (in order of importance):

Note: Try different ground connection locations before adjusting procedures.

1. Decrease torch angle.
2. Increase stickout.
3. Decrease voltage.
4. Decrease WFS (wire feed speed).
5. Decrease travel speed.

To Eliminate Stubbing* (in order of importance):

1. Increase voltage
2. Decrease WFS (wire feed speed)
3. Decrease stickout
4. Increase torch angle

* Stubbing occurs when the electrode drives through the molten puddle and hits the bottom plate tending to push the gun up.

Proper Gun Handling

Most feeding problems are caused by improper handling of the gun cable or electrodes.

1. Do not kink or pull the gun around sharp corners
2. Keep the gun cable as straight as practical when welding.
3. Do not allow dolly wheels or trucks to run over the cables.
4. Keep the cable clean.
5. Use only clean, rust-free electrode. Lincoln electrodes have proper surface lubrication.
6. Replace contact tip when it becomes worn or the end is fused or deformed.

Section 6 - MAINTENANCE



WARNING



ELECTRIC SHOCK can kill

- Have an electrician install and service this equipment.
- Turn the input power off at the fuse box, or unplug input lead before working on equipment.
- Do not touch electrically hot parts.

Flex the cable over its entire length and again blow out the cable. Repeat this procedure until no further dirt comes out.



CAUTION

Excessive pressure at the start may cause dirt to form a plug.

6.1 Routine Maintenance

General

In extremely dusty locations, dirt may clog the air passages and cause the welder to run hot. Blow dirt out of the welder with low-pressure air at regular intervals to eliminate excessive dirt and dust build-up on internal parts.

The fan motor has sealed ball bearings which require no service.

Welding Thermal Overload Protection

The REDI-MIG® has built-in protective thermostats that respond to excessive temperature. They open the wire feed and welder output circuits if the machine exceeds the maximum safe operating temperature because of a frequent overload, or high ambient temperature plus overload. The over temperature light on the control panel glows if thermostats open. The thermostats automatically reset when the temperature reaches a safe operating level. The fan will stay on when the machines welding and feeding are disabled during thermostatic over temperature protection.

6.2 Gun and Cable Maintenance

Cable Cleaning

Clean cable liner after using approximately 150kg of electrode. Remove the cable from the wire feeder and lay it out straight on the floor. Remove the contact tip from the gun. Using an air hose and approx. 350 kPa (50psi) pressure, gently blow out the cable liner from the gas diffuser end.

6.3 Gun Tips and Nozzles

The gun tip should be replaced when worn. Replace with the correct size for the wire type and diameter. Too large a tip for the electrode wire will cause arcing within the gun cable and possible jamming of the wire within the cable.

Remove spatter from inside of gas nozzle and from tip after each 10 minutes of arc time or as required.

Drive Rolls and Guide Tubes

After every coil of wire, inspect the wire drive mechanism. Clean it as necessary by blowing with low pressure compressed air. Do not use solvents for cleaning the idle roll because this may wash the lubricant out of the bearing. All drive rolls are stamped with the wire sizes they will feed. If a wire size other than that stamped on the roll is to be used, the drive roll must be changed.

Avoiding Wire Feeding Problems

Wire feeding problems can be avoided by observing the following gun handling procedures:-

1. Do not kink or pull gun cable around sharp corners.
2. Keep the gun cable as straight as possible when welding or feeding electrode through cable.
3. Keep gun cable clean by following maintenance instructions.
4. Use only clean, rust-free electrode. Lincoln Electric electrode has proper surface lubrication.
5. Replace contact tip when the arc starts to become unstable or the contact tip end is fused or deformed.

6.4 Input Lead

If the supply cord is damaged, it must be replaced with a special cord. Refer spare part list.

6.5 Liner Removal, Installation and Trimming Instructions for LINC Gun® 240 & 360 Torch

Note: The variation in cable lengths prevents the interchangeability of liners between guns. Once a liner has been cut for a particular gun, it should not be installed in another gun unless it can meet the liner cutoff length requirement.

1. Remove the gas nozzle and gas diffuser, (if used), to locate the set screw in the gas diffuser which is used to hold the old liner in place. Loosen the set screw with an Allen key.
2. Remove the contact tip holder from the gun tube.
3. Lay the gun and cable out straight on a flat surface. Loosen the liner nut cap located in the brass connector at the feeder end of the cable and pull the liner out of the cable.

4. Insert a new untrimmed liner into the connector end of the cable.
5. Fully seat the liner bushing into the Euro connector. Tighten the liner nut cap on the brass cable connector. The contact tip holder, at this time, should not be installed onto the end of the gun tube.
6. With the contact tip holder still removed from the gun tube, be sure the cable is straight, and then trim the liner to length. Remove any burrs from the end of the liner.
7. Screw the contact tip holder onto the end of the gun tube and securely tighten. Be sure the contact tip holder is correct for the tips being used.
8. Tighten the set screw in the side of the gas diffuser against the cable liner using an Allen key. **Do not overtighten.**

Section 7 - ACCESSORIES

- Drive Rolls for mild steel, stainless steel and aluminium for solid wires as well as for flux cored wires. See your nearest Lincoln distributor for details.
- 1.2mm Aluminium Welding Kit complete with 0.9mm, 1.2mm U-groove drive rolls, 0.9-1.2mm Teflon torch liner, packet of 10 X1.2mm contact tips, Teflon inlet and outlet guides (for REDI-MIG® 210c & 250c use KA1440-4 and for REDI-MIG® 250s, 325c & 325s use KA1440-5).
- 1.2mm Flux Cored, Gas and Gasless Welding Kit, complete with 0.9, 1.2mm knurled drive rolls, 0.9-1.2mm torch liner and packet of 10 x 1.2mm contact tips (for REDI-MIG® 210c & 250c use KA1441-4. For REDI-MIG® 250s, 325c & 325s use KA1441-5).

Section 8 - GROUND TEST PROCEDURE

These procedures refer to the REDI-MIG® 250s, 325c & 325s



WARNING

This procedure is only suitable for applications using DC mega testers up to 500V.



ELECTRIC SHOCK can kill

Note: This procedure is for 'machines as built' many modifications could have taken place over the life of a particular machine, so details of this procedure may need to be 'adjusted' to suit these modifications.

For prompt service contact your local Lincoln Field Service Shop.

The insulation resistance values listed below are from Australian Standard AS60974-1.

- 1) Disconnect input cable from power outlet.
- 2) Disconnect all output cables (control & weld).
- 3) Remove the roof panel.
- 4) Jumper the three (3) AC terminals and the (+) & (-) terminals of the three phase bridge rectifier (A total of five (5) places).

- 5) Jumper the four (4) meter terminals together.
- 6) Switch the fine control rotary switch to position '1' & switch the coarse control rotary switch to position '1'.
- 7) **Primary test:** Connect one lead of the mega tester to the frame of the machine and the other lead to each of the three (3) input conductors and to the main transformer primary leads L1A, L2A & L3A. Apply the test(s).
- 8) **Welding circuit test:** Connect one lead of the mega tester to the frame of the machine and the other lead to the positive output stud. Apply the test. (Min resistance 5.0MΩ).
- 9) **Welding circuit to primary test:** Connect one lead of the mega tester to the positive output stud and the other lead to each of the three (3) input conductors and to the main transformer primary leads L1A, L2A & L3A. Apply the test. (Min resistance 2.5MΩ).
- 10) **Transformer thermostat test:** Connect one lead of the mega tester to the frame of the machine and the other lead to the positive output stud. Apply the test. (Min resistance 1MΩ).
- 11) Remove all jumper leads.
- 12) Refit the roof panel.

Procedure for Replacing PC Boards

Before replacing a PC board suspected of being defective, visually inspect the PC board in question for any visible damage to any of its components and conductors on the back of the board.

1. If there is no visible damage to the PC board, install a new one and see if this remedies the problem. If the problem is remedied, reinstall the original PC board to see if the problem still exists. If the problem no longer exists with the old PC board:
 - a. Check the PC board harness connector pins for corrosion, contamination, or looseness.

- b. Check leads in the plug harness for loose or intermittent connection.
2. If PC board is visibly damaged, before possibly subjecting the new PC board to the same cause of failure, check for possible shorts, opens or grounds caused by:
 - a. Damaged lead insulation.
 - b. Poor lead termination, such as a poor contact or a short to adjacent connection or surface.
 - c. Shorted or open motor leads, or other external leads.
 - d. Foreign matter or interference behind the PC board.
 3. If PC board is visibly damaged, inspect for cause, then remedy before installing a replacement PC board.

Changing Settings for Motor Acceleration

If Motor Acceleration needs to be altered from factory setting, because of the welding procedure being used, locate the PCB in the REDI-MIG® 325c or REDI-MIG® 4s Remote Wire Feeder.

On the PCB there is a trimmer labelled 'Rampa', this trimmer controls the acceleration rate of the drive motor from stationary to the set wire feed speed. Maximum acceleration when fully counter-clockwise to minimum acceleration when fully clockwise. This is particularly important when welding aluminium wire. The factory setting is fully clockwise.

Section 8 - GROUND TEST PROCEDURE

The following procedures refer to the REDI-MIG® 210c & 250c



WARNING

This procedure is only suitable for applications using DC mega testers up to 500V.



ELECTRIC SHOCK can kill

Note: This procedure is for 'machines as built' many modifications could have taken place over the life of a particular machine, so details of this procedure may need to be 'adjusted' to suit these modifications.

For prompt service contact your local authorised Lincoln Electric Field Service Shop.

The insulation resistance values listed below are from Australian Standard AS60974.1.



- 1) Disconnect input cable from power supply.
- 2) Disconnect gun assembly and work cable.
- 3) Remove the side panel from power source.
- 4) Jumper the two (2) AC terminals and both output terminals of the bridge rectifier, (a total of three (4) places).
- 5) Disconnect the PCB plug.
- 6) Switch the control rotary switch to position 'one' (1) and switch the on/off switch to on.
- 7) **Primary Test:** Connect one lead of the mega tester to the frame of the machine and the other lead to the Active terminal of the input plug. Apply the test. (Min. resistance 2.5M Ω)
- 8) **Welding circuit test:** Connect one lead of the mega tester to the frame of the machine and the other lead to the (+)ve output stud. Apply the test. (Min. resistance 2.5M Ω)
- 9) **Welding circuit to primary test:** Connect one lead of the mega tester to the (+)ve output stud and the other lead to the Active terminal of the input plug. Apply the test. (Min. resistance 5M Ω)
- 10) **Transformer thermostat test:** Connect one lead of the mega to the frame of the machine and the other lead to the rectifier thermostat terminals. Apply the test. (Min. resistance 2.5M Ω)
- 11) Remove all jumpers and reconnect all leads and plugs.
- 12) Refit all panel work previously removed.

Procedure for Replacing PC Boards

Before replacing a PC board suspected of being defective, visually inspect the PC board in question for any visible damage to any of its components and conductors on the back of the board.

1. If there is no visible damage to the PC board, install a new one and see if this remedies the problem. If the problem is remedied, reinstall the original PC board to see if the problem still exists. If the problem no longer exists with the old PC board:
 - a. Check the PC board harness connector pins for corrosion, contamination, or looseness.
 - b. Check leads in the machine harness for loose or intermittent connection.
2. If PC board is visibly damaged, before possibly subjecting the new PC board to the same cause of failure, check for possible shorts, opens or grounds caused by:
 - a. Damaged lead insulation.
 - b. Poor lead termination, such as a poor contact or a short to adjacent connection or surface.
 - c. Shorted or open motor leads, or other external leads.
 - d. Foreign matter or interference behind the PC board.
3. If PC board is visibly damaged, inspect for cause, then remedy before installing a replacement PC board.

Section 9 - TROUBLESHOOTING

 WARNING	
	<ul style="list-style-type: none"> • Have an electrician install and service this equipment. • Turn the input power off at the fuse box and unplug the machine before working on equipment. • Do not touch electrically hot parts.
ELECTRIC SHOCK can kill	

Problem	Possible Cause	What To Do
Rough wire feeding or wire not feeding but drive rolls turning.	Gun cable kinked and/or twisted.	Inspect gun cable and replace if necessary.
	Wire jammed in gun and cable.	Remove wire from gun and cable - feed in new wire. Note any obstructions in gun and cable. Replace gun and cable if necessary.
	Incorrectly fitted drive roll.	See Wire Drive Roll Section in this manual for proper installation of drive roll.
	Drive roll loose.	Remove, clean, install and tighten.
	Gun cable dirty.	Clean cable or replace liner.
	Worn drive roll.	Replace.
	Electrode rusty and/or dirty.	Replace.
	Worn nozzle or cable liner.	Replace.
	Partially flashed or melted contact tip.	Replace contact tip.
Incorrect idle roll pressure.	Set idle roll pressure.	
Variable or “hunting” arc.	Wrong size, worn and/or melted contact tip.	Replace tip - remove any spatter on end of tip.
	Worn work cable or poor work connection.	Inspect - repair or replace as necessary.
	Loose electrode connections.	Be sure electrode lead is tight, gun cable tight in wire feeder contact block, gun nozzle and gun tip tight. All work lead connections must be tight.
	Wrong polarity.	Check connection at output studs for polarity required by welding process.
Poor arc striking with sticking or “blast offs”, weld porosity, narrow and ropey looking bead, or electrode stubbing into plate while welding.	Improper procedures or techniques.	See “Gas Metal Arc Welding Guide” (GS100).
	Improper gas shielding	<p>Clean gas nozzle. Make certain that gas diffuser is not restricted. Make certain that gas cylinder is not empty or turned off. Make certain gas solenoid valve is operating and gas flow rate is correct.</p> <p>Remove gun liner and check rubber seal for any sign of deterioration or damage. Be sure set screw in brass connector is in place and tightened against the liner bushing.</p>
Tip seizes in diffuser.	Tip overheating due to prolonged or excessive high current and/or duty cycle welding.	<p>Do not exceed current and duty cycle rating of gun.</p> <p>A light application of high temperature antiseize lubricant may be applied to tip threads.</p>

TROUBLESHOOTING

Problem	Possible Cause	What To Do
No wire feed, although arc voltage is present.	Defective wire feed motor or wire drive control PC board.	Measure the voltage between the motor leads (54) and (53) when the Gas Purge/Wire Inch toggle switch is pressed downwards. If this voltage is over 10V DC, replace the wire feed motor. If no voltage is registered, replace the wire drive PCB. (Refer PCB replacement procedure on page 19).
No control of wire feed.	Defective wire drive control PC board.	Replace PCB. (Refer PCB replacement procedure on page 19).
No wire feed and no arc voltage. Pilot light indicates input power to machine.	Overtemperature protection circuit actuated due to overload or short. (Overtemperature light should be illuminated).	Allow machine to cool down and reduce on time and/or wire feed speed.
	Faulty gun trigger switch or damaged control cable connected to gun trigger.	Repair.
	Defective control PC board.	Refer Procedure for Replacing PC Boards, if no fault is detected in trigger-thermostat circuit.
	Defective contactor	Replace defective contactor
Poor welding characteristics and/or cannot obtain full rated output as per nameplate.	Improper settings for wire feed speed and volts.	Set controls correctly.
	Faulty switch either coarse control (on/off) or fine control.	Replace switch.
	Faulty pilot transformer.	Replace.
	Faulty main transformer.	Replace.
	Faulty rectifier.	Replace
	Faulty choke.	Replace.
	One phase disconnected.	Check fuses, check input connection.

REDI-MIG PARTS LISTS AND WIRING DIAGRAMS INDEX

REDI-MIG® 210c & 250c

REDI-MIG® 210c & 250c PARTS ILLUSTRATION AND LIST	28
COVER PANELS ILLUSTRATION AND LIST	30
REDI-MIG® 210c & 250c WIRING DIAGRAM	31

REDI-MIG® 250s

REDI-MIG® 250s PARTS ILLUSTRATION AND LIST	32
COVER PANELS ILLUSTRATION AND LIST	34
REDI-MIG® 250s WIRING DIAGRAM	35

REDI-MIG® 325c

REDI-MIG® 325c PARTS ILLUSTRATION AND LIST	36
COVER PANELS ILLUSTRATION AND LIST	38
REDI-MIG® 325c WIRING DIAGRAM	39

REDI-MIG® 325s


REDI-MIG® 325s PARTS ILLUSTRATION AND LIST	40
COVER PANELS ILLUSTRATION AND LIST	42
REDI-MIG® 325s WIRING DIAGRAM	43

REDI-MIG® 4s

REDI-MIG® 4s PARTS ILLUSTRATION AND LISTS	44
REDI-MIG® 4s WIRE FEEDER WIRING DIAGRAM	46

REDI-MIG 210C & 250C PARTS LIST

SUB ASSEMBLY PAGE NAME		Wire Feed Assembly	Cover Panels	Wiring Diagram			
PARTS LIST							
CODE NO.	MODEL	AP224-C	AP224-D	AP228-W			
70169	RediMig 210C (K32048-1)	1	1	1			
70170	RediMig 250C (K32049-1)	2	2				




REDI-MIG 210C & 250C PARTS LIST

Indicates a change this printing.

Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	Moulded Handle Left Side	M51551-1L	1	X	X							
2	Handle	AS5032	1	X	X							
3	Moulded Handle Right Side	M51551-1R	1	X	X							
4	Rocker Switch	AM3990A	1	X	X							
5	Sealing Boot	AM3990B	1	X	X							
6	Control PCB	AS4966-2	1	X	X							
7	Expansion Nut	S14020-1A	4	X	X							
8	Thread Forming Screw	S9225-63A	4	X	X							
9	Knob	T10491	1	X	X							
10	REDI-MIG 210C Nameplate Engraved	AM3977	1	X								
	REDI-MIG 250c nameplate	AM3980			X							
11	Fastener Button	T14659-1A	2	X	X							
12	Front Panel	AL2857	1	X	X							
13	Button Hd. Socket Screw	AM3053-331	3	X	X							
14	REDI-MIG 2 Wheel Drive Assy	AM3993	1	X	X							
15	Cable -- Sec.Tap to Neg.Stud	AS4462-3	1	X	X							
16	Cord Strain Relief	AT3764-1	1	X	X							
17	Rectifier FullBridge	AL2480-4	1	X	X							
18	Lower Nameplate C Range	AM3973	1	X	X							
19	3/8" Flatwasher	S9262-120A	2	X	X							
20	Spacer Tube	AT4024-8	2	X	X							
21	Redimig 210&250 Capacitor Assy	AM3970	1	X	X							
22	REDI-MIG 210C Switch&Transformer Assy	AG1544-1	1	X	X							
	REDI-MIG 250C Switch&Transformer Assy	AG1544-2			X							
23	REDI-MIG Base Assy	AL2892	1	X	X							
24	REDI-MIG Baffle 210/250	AM3972	1	X	X							
25	REDI-MIG Rear Panel Single Fan	AL2868	1	X	X							
	REDI-MIG Double Fan	AL2869	1	X	X							
26	Fan 170mm	AM3809-2	1	X	X							
	Fan 170mm No.2	AM3809-2	1	X	X							
27	Gas Valve 240Vac	AS4967	1	X	X							
28	Cable Gland	AT3871-1	1	X	X							
29	.25in x .50inT/C Screw (Black)	S9225-68A	20	X	X							
30	Spool Post EasyMIGs	AS4970	1	X	X							
31	RediMig Bulkhead Panel	AL2863	1		X							
32	Bushing	T14614-2	1		X							
33	Plug Button	T10397-3A	1		X							
34	Bushing	T12380-4	1		X							
35	50A Contactor Switch	AM3879-2	1		X							
36	Resistor 100W	S10404-94	1		X							
37	Bushing	T14614-3	1		X							
38	REDI-MIG Shelf Panel	AL2856	1		X							
39	Choke Coil Assy	AM4005	1		X							
40	Hose 5mm (Black)	AS4150-23	1		X							
41	Hose Clamp	AT3061-10	1		X							
278	Input Lead 15A 240V	AS2373-9	1		X							

REDI-MIG COVER PANEL PARTS LIST



AP-244D.1

AP-244D.1

Indicates a change this printing.


Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	RH Lower Side Panel	AL2861	1	X	X	X	X	X				
2	LH Side Panel	AL2860	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546	1	X								
	Decal Side Stripe Set 250C	AG1554	1		X							
	Decal Side Stripe Set 250S	AG1553	1			X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
3	Black Screw .25" x .50"	S9225-68	21	X	X	X	X	X				
4	Roof Assembly	AL2859	1	X	X	X	X	X				
	Decal	AS4244	1	X	X	X	X	X				
		S52073-1	2	X	X	X	X	X				
		AT3425-2	2	X	X	X	X	X				
5	Access Door	AL2864	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546		X								
	Decal Side Stripe Set 250C	AG1554			X							
	Decal Side Stripe Set 250S	AG1553				X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
			1	X	X	X	X	X				
6	Knob (Supplied with Switch)	NSS	1	X	X	X	X	X				
ITEMS NOT SHOWN												
	Linc Gun LG240G 4m	K10413-24-4M	1	X	X	X						
	Linc Gun LG360G 4m	K10413-36-4M	1					X	X			
	Regulator Argon	LE250-RG002	1	X	X	X	X	X				
	Chain 27" Long	AT3873	1	X	X	X	X	X				
	Welding Guide 210	AM4016	1	X								
	Welding Guide 250	AM4017	1		X	X						
	Welding Guide 325	AM4019	1				X	X				

SWAP BLACK & RED FOR MOTOR, ADD J6, J5

AM4011

CHANGE DETAILS : REVISE T2, T3 CONNECTION



SW2

(N1)		X/T17	U/T18	Y/T18	V/T2	Z/T19	W/T3
(6)	(7)						

POS

1		X		X		X
2		X		X	X	X
3		X	X			X
4		X	X		X	X
5	X			X		X
6	X			X	X	X
7	X		X			X
8	X		X		X	X

N.A. CUT OFF TERMINAL AND INSULATE TO PROVIDE 600V INSULATION ONLY IN THE 250C/S.

DO NOT SCALE OFF DRAWING



THIS SHEET CONTAINS PROPRIETARY INFORMATION OWNED BY THE LINCOLN ELECTRIC CO. (AUST.) AND IS NOT TO BE REPRODUCED, DISCLOSED OR USED WITHOUT THE EXPRESS PERMISSION OF THE LINCOLN ELECTRIC CO. (AUST.)

UNLESS OTHERWISE STATED TOLERANCE ON HOLE SIZES PER E2056. ALL DIMENSIONS ARE 5 UNLESS OTHERWISE STATED. UNLESS ALL ANGLES ARE 5 OF A DEGREE. MATERIAL TOLERANCE TO AGREE WITH PUBLISHED STANDARDS.

CHANGE DATE

ALPHA	
BETA	
A03-09-08W	
A01-10-08C	
A17-12-08C	

THE LINCOLN ELECTRIC CO. (AUST.) PTY. LTD.
 PADSTOW, N.S.W. AUSTRALIA.

SCALE: NTS

DATE: 22-07-08

DRAWN: A.S.

CHK:

REF: AM3848

SUP'S'D'G:


TYPE: REDI-MIG 210C 250C
 SUBJECT: WIRING DIAGRAM

SHT. NO. AM4011

SOLID EDGE

REDI-MIG 250s PARTS LIST

SUB ASSEMBLY PAGE NAME		Wire Feed Assembly	Cover Panels	Wiring Diagram			
PARTS LIST							
CODE NO.	MODEL	AP225-C	AP224-D	AP225-W			
70171	REDI-MIG® 250s (K32049-2)	1	1	1			




REDI-MIG 250s PARTS LIST

Indicates a change this printing.

Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	Moulded Handle Left Side	M51551-1L	1	X								
2	REDI-MIG Handle	AS5032	1	X								
3	Moulded Handle Right Side	M51551-1R	1	X								
4	Sealing Boot	AM3990B	1	X								
5	Rocker Switch	AM3990A	1	X								
6	Light Diode & Resistor Assy	AS5021	1	X								
7	REDI-MIG 250S Nameplate Engraved	AM3982	1	X								
8	Fastener Button	T14659-1A	2	X								
9	REDI-MIG Front Panel	AL2857	1	X								
10	.25in x .50inT/C Screw (Black)	S9225-68A	15	X								
11	Rectifier FullBridge	AL2480-4	1	X								
12	Lower Nameplate S Range	AM3978	1	X								
13	Plug Base & Resistor Assy	AS4407-10	1	X								
14	Spacer Tube	AT4024-8	2	X								
15	REDI-MIG 250C/S Switch&Transformer Assy	AG1544-2	1	X								
16	REDI-MIG 210 & 250 Capacitor Assy	AM3970	1	X								
17	REDI-MIG Baffle 210/250	AM3972	1	X								
18	REDI-MIG Base Assy	AL2892	1	X								
19	S/T Screw Hex	S8025-91A	6	X								
20	Fan 170mm MIGs	AM3809-2	2	X								
21	Input Lead 15A 240V	AS2373-9	1	X								
22	Plug Button	T10397-3A	2	X								
23	Cable Gland	AT3871-1	1	X								
24	REDI-MIG Rear Panel DoubleFan	AL2869	1	X								
25	REDI-MIG Bulkhead Panel	AL2863	1	X								
26	Bushing	T14614-2	1	X								
27	Buffer Grommet	AS4404-4	3	X								
28	Aux Transformer 240/42v	AM4000-2	1	X								
29	Hole Plug	T13597-1	2	X								
30	Delexi 42V Contactor	AM3879-3	1	X								
31	Redimig 210/250/C/S Choke Coil Assy	AM4005	1									
32	Resistor 100W	S10404-94	1									
33	REDI-MIG Shelf Panel	AL2856	1									

REDI-MIG COVER PANEL PARTS LIST



AP-244D.1

AP-244D.1


Indicates a change this printing.

Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	RH Lower Side Panel	AL2861	1	X	X	X	X	X				
2	LH Side Panel	AL2860	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546	1	X								
	Decal Side Stripe Set 250C	AG1554	1		X							
	Decal Side Stripe Set 250S	AG1553	1			X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
3	Black Screw .25" x .50"	S9225-68	21	X	X	X	X	X				
4	Roof Assembly	AL2859	1	X	X	X	X	X				
	Decal	AS4244	1	X	X	X	X	X				
		S52073-1	2	X	X	X	X	X				
		AT3425-2	2	X	X	X	X	X				
5	Access Door	AL2864	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546		X								
	Decal Side Stripe Set 250C	AG1554			X							
	Decal Side Stripe Set 250S	AG1553				X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
			1	X	X	X	X	X				
6	Knob (Supplied with Switch)	NSS	1	X	X	X	X	X				
ITEMS NOT SHOWN												
	Linc Gun LG240G 4m	K10413-24-4M	1	X	X	X						
	Linc Gun LG360G 4m	K10413-36-4M	1				X	X				
	Regulator Argon	LE250-RG002	1	X	X	X	X	X				
	Chain 27" Long	AT3873	1	X	X	X	X	X				
	Welding Guide 210	AM4016	1	X								
	Welding Guide 250	AM4017	1		X	X						
	Welding Guide 325	AM4019	1				X	X				

AM4012


CHANGE DETAILS : SWAP R1,R2 CHG N2 TO H2, A2 TO H1 ADD A2, N2. DEL DIODE.



N.A. CUT OFF TERMINAL AND INSULATE TO PROVIDE 600V. INSULATION.

SW2							
(N)	X/T7	U/T1	Y/T8	V/T2	Z/T9	W/T3	
(6)	(7)		(5)	(3)	(4)		
1	X		X		X		X
2	X		X	X			X
3	X	X					X
4	X	X			X		X
5	X			X			X
6	X			X	X		
7	X		X				X
8	X		X		X		

DO NOT SCALE OFF DRAWING



THIS SHEET CONTAINS PROPRIETARY INFORMATION OWNED BY THE LINCOLN ELECTRIC CO. (AUST.) AND IS NOT TO BE REPRODUCED, DISCLOSED OR USED WITHOUT THE EXPRESS PERMISSION OF THE LINCOLN ELECTRIC CO. (AUST.)

UNLESS OTHERWISE STATED TOLERANCE ON HOLE SIZES PER E2056. ALL DIMENSIONS ±.5 UNLESS OTHERWISE STATED. ON ALL ANGLES 1st .5 OF A DEGREE. MATERIAL TOLERANCE TO AGREE WITH PUBLISHED STANDARDS.


CHANGE DATE: ALPHA BETA A03-09-08W A22-10-08H

THE LINCOLN ELECTRIC CO. (AUST.) PTY. LTD.
 PADSTOW, N.S.W. AUSTRALIA.
 SCALE: NTS. DATE: 22-07-08
 SUBJECT: WIRING DIAGRAM
 DRAWN: A.S. CHK: REF: AM3848 SUP'S'D'G: SHIT. NO. AM4012

SOLID EDGE

REDI-MIG 325C WIRE FEEDER PARTS LIST


SUB ASSEMBLY PAGE NAME		Wire Feed Assembly	Cover Panels	Wiring Diagram			
PARTS LIST							
CODE NO.	MODEL	AP227-C	AP224-D	AP227-W			
70173	REDI-MIG® 325c (K32050-2)	1	1	1			



REDI-MIG 325c PARTS LIST

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8
1	Moulded Handle Left Side	M51551-1L	1	X							
2	REDI-MIG Handle	AS5032	1	X							
3	Moulded Handle Right Side	M51551-1R	1	X							
4	Voltmeter 0-50V DC	AM3397-1	1	X							
5	Ammeter 0-400A DC	AM3398-1	1	X							
6	Rocker Switch	AM3990A	1	X							
7	Sealing Boot	AM3990B	1	X							
8	Light Diode & Resistor Assy	AS5021	1	X							
9	Knob	S18425-1	2	X							
10	Knob Large (Supplied With Switch)	AM3388A	2	X							
11	Fastener Button	T14659-1A	3	X							
12	REDI-MIG 325C Nameplate	AM3986	1	X							
13	Cable -- Sec.Tap to Neg.Stud	AS4462-3	1	X							
14	Cord Strain Relief	AT3764-1	1	X							
15	REDI-MIG Front Panel	AL2857	1	X							
16	Bushing	T14614-3	1	X							
17	Buffer Grommet	AS4404-4	1	X							
18	42V-4 Wheel Greared Drive Plate Assy	AM3994	1	X							
19	Lower Nameplate C Range	AM3973	1	X							
20	Potentiometer	AS4212-2	1	X							
21	REDI-MIG Shelf Panel	AL2856	1	X							
22	Left Bracket	AM3969 L	1	X							
23	Right Bracket	AM3969 R	1	X							
24	REDI-MIG 325 C/S Rectifier To Stud Strap	AS5035	1	X							
25	Shunt 400 Amp	S6602-22	1	X							
26	Bracket Rear	AM3968	1	X							
27	Base Assy	AL2892	1	X							
28	Switch&Transformer Assy	AG1559	1	X							
29	Fan 170mm MIGs	AM3809-2	2	X							
30	S/T Screw Hex	S8025-91A	6	X							
31	Input Lead REDI-MIG 325C/S	AS4303	1	X							
32	Gas Valve 42V	AS5016	1	X							
33	Cable Gland	AT3871-1	1	X							
34	REDI-MIG Rear Panel DoubleFan	AL2869	1	X							
35	Hose 5mm (Black)	AS4150-23	1	X							
36	Rectifier REDI-MIG 325C/S	AL2877	1	X							
37	REDI-MIG 325 C/S Chokel Assy	AM4006	1	X							
38	Bushing	T14614-2	1	X							
39	REDI-MIG Bulkhead Panel	AL2858	1	X							
40	AUX TRANSFORMER 415V/240V/42V	AM4000-1	1	X							
41	Spool Post	AS4970	1	X							
42	Contacto	AM3879-3	1	X							
43	Expansion Nut	S14020-1A	4	X							
44	Burnback Decal	AS4707-1	1	X							
45	Plug Button	T10397-3A	1	X							
46	Bushing	T12380-4	1	X							
47	Burnback Pot. Assembly	AS4711	1	X							
48	Motor Control PCB / Burnback Header	AS4212-5	1	X							

REDI-MIG COVER PANEL PARTS LIST



AP-244D.1

AP-244D.1


Indicates a change this printing.

Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	RH Lower Side Panel	AL2861	1	X	X	X	X	X				
2	LH Side Panel	AL2860	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546	1	X								
	Decal Side Stripe Set 250C	AG1554	1		X							
	Decal Side Stripe Set 250S	AG1553	1			X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
3	Black Screw .25" x .50"	S9225-68	21	X	X	X	X	X				
4	Roof Assembly	AL2859	1	X	X	X	X	X				
	Decal	AS4244	1	X	X	X	X	X				
		S52073-1	2	X	X	X	X	X				
		AT3425-2	2	X	X	X	X	X				
5	Access Door	AL2864	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546		X								
	Decal Side Stripe Set 250C	AG1554			X							
	Decal Side Stripe Set 250S	AG1553				X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
			1	X	X	X	X	X				
6	Knob (Supplied with Switch)	NSS	1	X	X	X	X	X				
ITEMS NOT SHOWN												
	Linc Gun LG240G 4m	K10413-24-4M	1	X	X	X						
	Linc Gun LG360G 4m	K10413-36-4M	1					X	X			
	Regulator Argon	LE250-RG002	1	X	X	X	X	X				
	Chain 27" Long	AT3873	1	X	X	X	X	X				
	Welding Guide 210	AM4016	1	X								
	Welding Guide 250	AM4017	1		X	X						
	Welding Guide 325	AM4019	1				X	X				

AM4013

CHANGE DETAILS : CHG H3, H2A,H1 TO SUITE PILOT TRANSFORMER




SW1 OFF / COURSE						
L3A	L2A	L1A				
T/L3	S/L2	R/L1				
Z/T9	W/T3	Y/T8	V/T2	X/T7	U/T1	
(9)	(2)	(8)	(1)	(7)	(10)	
POS						
1	X		X		X	
2	X		X	X		
3	X	X	X			
4	X		X		X	

SW2 FINE						
X/T7	U/T1	Y/T8	Y/T2	Z/T9	W/T3	
(4)	(1)	(5)	(2)	(6)	(3)	
POS						
1	X		X		X	
2	X		X	X		
3	X	X	X		X	
4	X	X		X		
5	X		X		X	
6	X		X	X		
7	X	X			X	
8	X		X		X	

N.A. LEADS TO BE TWISTED TOGETHER FULL LENGTH.
 N.B. UNITS VIEWED FROM REAR.

DO NOT SCALE OFF DRAWING



THIS SHEET CONTAINS PROPRIETARY INFORMATION OWNED BY THE LINCOLN ELECTRIC CO. (AUST.) AND IS NOT TO BE REPRODUCED, DISCLOSED OR USED WITHOUT THE EXPRESS PERMISSION OF THE LINCOLN ELECTRIC CO. (AUST.)

UNLESS OTHERWISE STATED TOLERANCE ON HOLE SIZES PER E2056. ALL DIMENSIONS ±.5 UNLESS OTHERWISE STATED. ON ALL ANGLES IS ±.5 OF A DEGREE. MATERIAL TOLERANCE TO AGREE WITH PUBLISHED STANDARDS.

CHANGE DATE					
ALPHA					
BETA					
A03-09-08W					
A12-11-08Q					

THE LINCOLN ELECTRIC CO. (AUST.) PTY. LTD.

PADSTOW, N.S.W. AUSTRALIA.

SCALE: NTS. DATE: 19-08-08


EQUIP TYPE: REDIMIG 325C
 SUBJECT: WIRING DIAGRAM

DRAWN: A.S. CHK: REF: AM3596-4 SUP'D'G: SHT. NO. AM4013

SOLID EDGE

REDI-MIG 325s PARTS LIST


SUB ASSEMBLY PAGE NAME		Wire Feed Assembly	Cover Panels	Wiring Diagram			
PARTS LIST							
CODE NO.	MODEL	AP226-C	AP224-D	AP226-W			
70172	REDI_MIG® 325s (K32050-2)	1	1	1			



REDI-MIG 325s PARTS LIST

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	Moulded Handle Left Side	M51551-1L	1	X								
2	Handle	AS5032	1	X								
3	Moulded Handle Right Side	M51551-1R	1	X								
4	Rocker Switch	AM3990A	1	X								
5	Sealing Boot	AM3990B	1	X								
6	Light Diode & Resistor Assy	AS5021	1	X								
7	325S Nameplate	AM3989	1	X								
8	Fastener Button	T14659-1A	2	X								
9	REDI-MIG Front Panel	AL2857	1	X								
10	Rectifier To Stud Strap	AS5035	1	X								
11	Lower Nameplate S Range	AM3978	1	X								
12	Right Bracket	AM3969 R	1	X								
13	Left Bracket	AM3969 L	1	X								
14	Plug Base & Resistor Assy	AS4407-9	1	X								
15	Transformer & Switch	AG1559	1	X								
16	Bracket Rear	AM3968	1	X								
17	Base Assy	AL2892	1	X								
18	Rectifier	AL2877	1	X								
19	Fan 170mm MIGs	AM3809-2	2	X								
20	S/T Screw Hex	S8025-91A	6	X								
21	Cable Gland	AT3871-1	1	X								
22	Plug Button	T10397-3A	2	X								
23	Input Lead	AS4303	1	X								
24	Rear Panel DoubleFan	AL2869	1	X								
25	Bushing	T14614-2	1	X								
26	Bulkhead Panel	AL2863	1	X								
27	Chokel Assy	AM4006	1	X								
28	Aux Transformer 415v/240v/42v	AM4000-1	1	X								
29	Contacto	AM3879-3	1	X								
30	Buffer Grommet	AS4404-4	4	X								
31	Hole Plug	T13597-1	2	X								
32	Shelf Panel	AL2856	1	X								

REDI-MIG COVER PANEL PARTS LIST



AP-244D.1

AP-244D.1


Indicates a change this printing.

Use only the parts marked "x" in the column under the heading number called for in the model index page.

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	RH Lower Side Panel	AL2861	1	X	X	X	X	X				
2	LH Side Panel	AL2860	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546	1	X								
	Decal Side Stripe Set 250C	AG1554	1		X							
	Decal Side Stripe Set 250S	AG1553	1			X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
3	Black Screw .25" x .50"	S9225-68	21	X	X	X	X	X				
4	Roof Assembly	AL2859	1	X	X	X	X	X				
	Decal	AS4244	1	X	X	X	X	X				
		S52073-1	2	X	X	X	X	X				
		AT3425-2	2	X	X	X	X	X				
5	Access Door	AL2864	1	X	X	X	X	X				
	Decal Side Stripe Set 210C	AG1546		X								
	Decal Side Stripe Set 250C	AG1554			X							
	Decal Side Stripe Set 250S	AG1553				X						
	Decal Side Stripe Set 325C	AG1555	1				X					
	Decal Side Stripe Set 325S	AG1556	1					X				
			1	X	X	X	X	X				
6	Knob (Supplied with Switch)	NSS	1	X	X	X	X	X				
ITEMS NOT SHOWN												
	Linc Gun LG240G 4m	K10413-24-4M	1	X	X	X						
	Linc Gun LG360G 4m	K10413-36-4M	1				X	X				
	Regulator Argon	LE250-RG002	1	X	X	X	X	X				
	Chain 27" Long	AT3873	1	X	X	X	X	X				
	Welding Guide 210	AM4016	1	X								
	Welding Guide 250	AM4017	1		X	X						
	Welding Guide 325	AM4019	1				X	X				

AM4014

CHANGE DETAILS :CHG H3, H2A,H1 TO SUITE PILOT TRANSFORMER




SW1 OFF / COURSE					
L3A	L2A	L1A	T/L3	S/L2	R/L1
Z/T9	W/T3	Y/T8	V/T2	X/T7	U/T1
(9)	(12)	(8)	(11)	(7)	(10)
POS					
1	X		X		X
2	X		X	X	
3	X	X		X	X
4	X		X		X

SW2 FINE					
X/T7	U/T1	Y/T8	Y/T2	Z/T9	W/T3
(4)	(1)	(5)	(2)	(6)	(3)
POS					
1		X		X	
2		X		X	X
3		X	X		X
4		X	X		X
5	X			X	X
6	X			X	X
7	X		X		X
8	X		X		X

N.B. UNITS VIEWED FROM REAR.
N.C. CUT OFF TERMINAL AND INSULATE TO PROVIDE 600V. INSULATION.

DO NOT SCALE OFF DRAWING



THIS SHEET CONTAINS PROPRIETY INFORMATION OWNED BY THE LINCOLN ELECTRIC CO. (AUST.) AND IS NOT TO BE REPRODUCED, DISCLOSED OR USED WITHOUT THE EXPRESS PERMISSION OF THE LINCOLN ELECTRIC CO. (AUST.)

UNLESS OTHERWISE STATED TOLERANCE ON HOLE SIZES PER ISO268. ALL DIMENSIONS ± 5 UNLESS OTHERWISE STATED. ON ALL ANGLES IS ± 5 OF A DEGREE. MATERIAL TOLERANCE TO AGREE WITH PUBLISHED STANDARDS.


CHANGE DATE					
ALPHA					
BETA					
A03-09-08W					
A12-11-08Q					

THE LINCOLN ELECTRIC CO. (AUST.) PTY. LTD.
PADSTOW, N.S.W. AUSTRALIA.
SCALE: NTS DATE: 19-08-08
DRAWN: A.S. CHK: REF: AM3569-4

EQUIP. TYPE: REDIMIG 325S
SUBJECT: WIRING DIAGRAM
SHT. NO. AM4014
SOLID EDGE

REDI-MIG 4s WIRE FEEDER PARTS LIST

SUB ASSEMBLY PAGE NAME		Wire Feed Assembly	Wiring Diagram			
PARTS LIST						
CODE NO.	MODEL	AP224-C	AP228-W			
70174	REDI-MIG® 4s (K32051-1)	1	1			




REDI-MIG 4s WIRE FEEDER PARTS LIST

ITEM	DESCRIPTION	PART NUMBER	QTY	1	2	3	4	5	6	7	8	9
1	Nameplate	AM3995	1	X								
2	Rubber Gromet	AT2853	2	X								
3	Fastener Button	T14659-1A	4	X								
4	Bulkhead	AL2865	1	X								
5	Knob	S18425-1	2	X								
6	Burnback Decal	AS4707-1	1	X								
7	4S Interconnection Cables	AL2901	1	X								
8	Potentiometer	AS4212-2	1	X								
9	Spool Post	AS4970	1	X								
10	4S Base+Front&Rear	AG1541	1	X								
11	Insulation	T12792-1	1	X								
12	Vibro Insulator	AS4404-3	4	X								
13	DPDT Toggle Switch (Sprung)	AS4706	1	X								
14	SPDT Toggle Switch	T13562	1	X								
15	42V-4 Wheel Greared Drive Plate Assy	AM3994	1	X								
16	Gas Valve 42V	AS5016	1	X								
17	Door Latch	AS5018	2	X								
18	Decal Weld Guide 4S	AM4020	1	X								
19	RediMig 4S Remote Side Stripe L	AG1551	1	X								
20	Warning Decal	AS4244	1	X								
21	4S Door	AL2866	1	X								
22	4S Roof	AM3967	1	X								
23	Hinge Plastic	S52073-1	2	X								
24	Handle	M15446	1	X								
25	4S Side Panel	AL2867	1	X								
26	4S Wiring Diagram.	AM4015	1	X								
27	Motor Control PCB / Burnback Header	AS4212-5SP	1	X								
28	RediMig 4S Remote Side Stripe R	AG1551	1	X								
29	Expansion Nut	S14020-1A	4	X								
30	Burnback Pot. Assembly	AS4711	1	X								


AM4015

CHANGE DETAILS : CHG TO SUITE HARNESS.



N.A.: UNITS VIEWED FROM REAR OF PANEL.

DO NOT SCALE OFF DRAWING



THIS SHEET CONTAINS PROPRIETARY INFORMATION OWNED BY THE LINCOLN ELECTRIC CO. (AUST.) AND IS NOT TO BE REPRODUCED, DISCLOSED OR USED WITHOUT THE EXPRESS PERMISSION OF THE LINCOLN ELECTRIC CO. (AUST.)

UNLESS OTHERWISE STATED TOLERANCE ON HOLE SIZES PER E2056. ALL DIMENSIONS ARE UNLESS OTHERWISE STATED.
ON ALL ANGLES IS ±.5 OF A DEGREE.
MATERIAL TOLERANCE TO AGREE WITH PUBLISHED STANDARDS.

CHANGE DATE	BY	REASON
ALPHA		
BETA		
A10-09-08H		
A15-10-08N		

THE LINCOLN ELECTRIC CO. (AUST.) PTY. LTD.
 PADSTOW, N.S.W. AUSTRALIA.
 SCALE: NTS DATE: 28-08-08
 SUBJECT: WIRING DIAGRAM
 DRAWN: A.S. CHK: S.W. REF: AM3596-5 SUP'S'DG.:
 SHT. NO. AM4015

SOLID EDGE

STATEMENT OF LIMITED WARRANTY

The Lincoln Electric Company (Australia) Pty Limited ("Lincoln") warrants all new machinery and equipment ("goods") manufactured by Lincoln against defects in workmanship and material subject to certain limitations hereinafter provided.

This warranty is void if Lincoln or its Authorised Service Facility finds that the equipment has been subjected to improper installation, improper care or abnormal operations.

PERIOD OF WARRANTY "LINCOLN BRANDED GOODS"

The period from the commencement of the warranty in respect of goods covered by this warranty shall be as follows:

Three Years

All Lincoln welding machines, wire feeders and plasma cutting machines unless listed below.

Two Years

All Weldanpowers, Rangers and Italian Invertec welders.

One Year

Italian Plasmas.

- All water coolers (internal and external).
- Arc welding and cutting robots and robotic controllers.
- All stick electrodes, welding wires and fluxes.
- All Environmental Systems equipment, including portable units, central units and accessories. (Does not include consumable items listed under 30-day warranty).
- All welding and cutting accessories including wire feed modules, undercarriages, field installed options that are sold separately, unattached options, welding supplies, standard accessory sets, replacement parts. (Does not include expendable parts and guns/torches listed under 90 and 30 day warranties)
- All "Pro Torch" TIG torches.

90 Days

- All Gun and Cable Assemblies (manufactured by Lincoln) and Spool guns.
- All MIG, TIG and Plasma Torches

30 Days

- All consumable items that may be used with the environmental systems described above. This includes hoses, filters, belts and hose adapters.
- Expendable Parts - Lincoln is not responsible for the replacement of any expendable part that is required due to normal wear.

ENGINE WARRANTY

To the extent permitted by law Lincoln shall be entitled to in its absolute discretion repair all engines and engine accessories however Lincoln shall not be held responsible for any such repair which shall be the sole responsibility of the engine manufacturer which provides for warranties for the period and subject to any limitations provided for by those manufacturers of the respective engines and engine accessories.

Three Years*

Deutz 912 Engine and Accessories
(Warranty service can only be carried out an authorised Deutz service dealer)

*Subject to conditions imposed by Deutz.

Cummins B3.3 Engine and Accessories
(Warranty service can only be carried out an authorised Cummins service dealer)

*Subject to conditions imposed by Cummins

Two Years

Perkins Engines and Accessories
(The Perkins Distributor Organisation provides all warranty service (accessories included) for the Perkins Engines powering goods manufactured by Lincoln.

*Subject to conditions imposed by Perkins

Briggs & Stratton Vanguard Engines and Accessories. (Warranty service can only be carried out by an authorised Briggs & Stratton service dealer).

*The Magnetron ignition system is warranted by Briggs & Stratton for 5 years.

Kubota Engines and Accessories
(Warranty service can only be carried out an authorised Kubota service dealer)

*Subject to conditions imposed by Kubota.

One Year*

Ruggerini Engines and Accessories
(Warranty service can only be carried out by authorised Lincoln Field Service Shop or the engine distributors authorised by the Lincoln branch office).

BATTERY WARRANTY

Lincoln supplies certain batteries in connection with its supply of goods and the purchaser acknowledges that any such battery is warranted by its manufacturer and any claim in respect of such a battery whether as to a defect in the battery or as to damage consequential upon a defect in a battery shall be made by the purchaser to the manufacturer of the battery and the purchaser shall not hold Lincoln in any way liable for the operation, non-operation or malfunction of any such battery.

CONDITION OF WARRANTY**TO OBTAIN WARRANTY COVERAGE:**

The purchaser must contact Lincoln or Lincoln's Authorised Service Facility about any defect claimed under Lincoln's warranty.

Determination of warranty on welding and cutting equipment will be made by Lincoln or Lincoln's Authorised Service Facility.

WARRANTY REPAIR

If Lincoln or Lincoln's Authorised Service Facility confirms the existence of a defect covered by this warranty, the defect will be corrected by repair or replacement at Lincoln's option.

At Lincoln's request, the purchaser must return, to Lincoln or its Authorised Service Facility, any "Goods" claimed defective under Lincoln's warranty.

FREIGHT COSTS

The purchaser is responsible for shipment to and from the Lincoln Authorised Service Facility.

WARRANTY LIMITATIONS

Certain conditions warranties and obligations are implied by law (for example under the Trade Practices Act 1974) and cannot be excluded or modified ("the statutory warranties").

Where the statutory warranties do apply then any express warranties given by Lincoln (the "express warranties") are given in addition and without derogation from the statutory warranties. Apart from the express warranties and (in cases where they apply by law but not otherwise) the statutory warranties Lincoln gives no warranties whether express or implied by operation of law or otherwise in respect of any goods manufactured or supplied by Lincoln or by its authorised distributor.

Any warranty whether express or statutory and the term of any such warranty as set out herein commences on the date Lincoln or Lincoln's authorised distributorship forwards the goods from the premises of Lincoln or Lincoln's authorised distributor to the purchaser.

In respect of any claim under the warranty herein provided a purchaser must furnish Lincoln with written notice of any claim under the warranty within the time period of the warranty as further specified herein.

The extent of Lincoln's warranty whether express or statutory is limited to a liability to repair, replace or pay to the purchaser an amount equal to:

- a) The cost of replacing the goods;
- b) The cost of obtaining equivalent goods; or
- c) The cost of having the goods repaired whichever remedy in its absolute discretion Lincoln chooses.

Upon request by Lincoln the purchaser must permit Lincoln to inspect the goods the subject of any claim under this warranty and Lincoln may at its absolute discretion repair or replace the goods F.O.B. at its own premises or at such other premises as Lincoln may designate provided that all freight charges to and from Lincoln's premises or such other premises as Lincoln may designate shall be paid by the purchaser.

Subject to the express and statutory warranties hereinbefore provided Lincoln provides no other warranties in respect of the manufacture or sale of goods and in particular Lincoln shall have no responsibility or liability in respect of:

- a) Repairs done to Lincoln's goods and undertaken by the purchaser outside Lincoln's premises without written authority from Lincoln obtained prior to any such repair;
- b) Any damage or failure of the goods as a result of normal wear and tear or the neglect misuse abuse or failure to properly service goods by any purchaser.

The liability of Lincoln is limited as hereinbefore provided and Lincoln shall not be liable for any incidental special or consequential damage suffered by a purchaser whether or not arising out of circumstances known or foreseeable known by Lincoln and in particular arising out of the supply of goods to a purchaser or the use of goods by a purchaser whether based on breach of contract negligence or tort.

CUSTOMER ASSISTANCE POLICY

The business of The Lincoln Electric Company is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for advice or information about their use of our products. We respond to our customers based on the best information in our possession at that time. Lincoln Electric is not in a position to warrant or guarantee such advice and assumes no liability, with respect to such information or advice. We expressly disclaim any warranty of any kind, including any warranty of fitness for any customer's particular purpose, with respect to such information or advice. As a matter of practical consideration, we also cannot assume any responsibility for updating or correcting any such information or advice once it has been given, nor does the provision of information or advice create, expand or alter any warranty with respect to the sale of our products.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying this type of fabrication methods and service requirements.

In Australia, Lincoln Technical Sales Representatives are located in, Mackay, Bundaberg, Brisbane, Newcastle, Sydney, Wollongong, Melbourne, Adelaide and Perth. To contact your local Lincoln Technical Sales Representative, call 1300 728 720 (for the cost of a local call). Lincoln products are sold primarily through its distributors. Our Regional Office locations are:

Northern Region: Unit 1/15 Westgate St, Wacol, Qld, 4076 (07) 3271 3000

Central Region: 35 Bryant Street, Padstow, NSW, 2211 (02) 9772 7222

Southern Region: 8/2 Sarton Rd, Clayton VIC 3168 (03) 9590 0143

Western Region: 25 Barker Street, Belmont, WA, 6104 (08) 9277 8744

New Zealand: 7B/761 Great South Road, Penrose, Auckland (9) 580 4008

Singapore: No.195, Lane 5008, Hutai Road, +86 21 66026620

Baoshan, Shanghai, China 201907



THE WELDING EXPERTSSM

**The Lincoln Electric Company
(Australia) Pty. Ltd.** A.B.N. 36 000 040 308

35 Bryant Street, Padstow, Sydney 2211, Australia

Telephone: (02) 9772 7222 Fax: (02) 9792 2420

International: Ph: +61 2 9772 7222 Fax: +61 2 9792 2420

THE LINCOLN ELECTRIC CO.

Cleveland, Ohio, U.S.A. - Subsidiary companies established in Australasia, Asia, Canada, Europe, North and South America.