



Industrial cylinder identification colours




INDUSTRIAL Cylinder Identification Colours



NITROGEN Based Cylinder Identification Colours



ARGON Based Cylinder Identification Colours



* If H₂ in mixture BS341 No 2/4 valve is installed.

** H₂ >3 % (Signal Red Shoulder), H₂ ≤ 3% (Signal Red Band).



Tubed cylinder indicated with silver line.

Gas Type	Valve Outlet Connection
Oxygen, Argon, Industrial Air, Nitrogen, Oxygen Free Nitrogen, Argon-Based Mixture & Nitrogen-Based Mixture	BS 341, No. 3
Dissolved Acetylene	BS 341, No. 2
Hydrogen	BS 341, No. 4
Carbon Dioxide	BS 341, No. 8

These colour codes serve as a guide only, the full chemical name are shown on cylinder labels.



INFO GATHERED WITH CARE AND KNOWLEDGE AVAILABLE ON THE DATE OF ISSUE.
 LINDE WARRANTIES ARE EXCLUDED.
 LINDE RESPONSIBILITY DOES NOT SUBSTITUTE USERS' RESPONSIBILITY.



Linde Malaysia Sdn Bhd [Registration No. 198301005160 (100783-W)]

Level 13, The Pinnacle, Persiaran Lagoon, Bandar Sunway, 47500 Petaling Jaya, Selangor Darul Ehsan, Malaysia.

Phone +60.3.5624-8888, Fax +60.3.5611-3512 Customer Service Centre: Tel : 1-800-883-888 Fax : 1-800-888-801 www.linde.com.my